Barkee Inspection Services, Inc.

"You've discovered a House: Let Us confirm it's Your Home. 3504 NW 113th Street

office (360) 574-5600

Vancouver, WA 98685 www.BarkeeInspect.com

OCHI #503 / OR CCB #153121

fax (360) 258-8397

KITCHEN & LAUNDRY

SCOPE: The inspection of refrigerators, stand-alone freezers, washers, dryers, and portable appliances including microwaves and dishwashers are outside the scope of this inspection. Oven self-cleaning operations, cooking functions, clocks, timing devices, lights, thermostat accuracy, and adequacy of builtin microwaves and dishwashers are not tested during this inspection. Appliances are not moved during the inspection, therefore the floor and walls behind these units are not inspected.

NOTE: If the future operation of the kitchen appliances is of concern, we recommend that you invest in a home warranty policy designed for repair/replacement of mechanical item failures in the home. The appliance testing that was performed was done as a courtesy and should not be considered as "Technically Exhaustive." It is also important to obtain any available appliance operation manuals.

GENERAL KITCHEN

WITH EATING AREA: Yes.

LOCATION: Main Floor.

REFRIGERATOR SPACE: Approx. 36" wide x 72" high.

WALL FINISH: Good.

Wood flooring condition is Good. FLOORING:

Dual pane window(s) condition is Good. WINDOWS:

The left window pane has lost its dual pane thermo-seal (x1). WINDOW DAMAGE:

The room lighting is adequate and functioning. LIGHTING:

Functioning as designed. **OUTLETS:**

GFCI OUTLETS: A GFCI outlet is provided but it is malfunctioning = The button does not

trip = HAZARD = Replace/Repair.

Heat register(s) noted. **HEATING DEVICE:**

CABINETS:

CABINET HARDWARE: Broken drawer guides: (x1) Below cutting board.

COUNTERTOPS: Good. SINK: Good.

DRAIN CONDITION: The following conditions were noted at the drain: Drainage is a bit slower

than normal = Clean the drain line.

FAUCET: Good.

None were visible at this time. **PLUMBING LEAKS:**

KITCHEN APPLIANCES

Yes. The dishwasher was cycled on the normal cycle to check for its operation DISHWASHER:

and to identify any leakage. Each cycle and feature of the unit was not tested =

Beyond the scope of this evaluation.

Functioning: Yes. GARBAGE DISPOSAL:

STOVE (RANGE): Electric: Functioning. The unit was turned on to check to see if the elements

heated up. The temperature settings and timer were not evaluated.

OVEN: Electric: Functioning. The unit was turned on to check to see if the elements

heated up. The temperature settings and timer were not evaluated.

Recirculating style - Functioning: Yes. The fan was turned on, tested, and then **EXHAUST FAN:**

turned back off.

REFRIGERATOR: Did Not Evaluate. The evaluation of refrigerator/freezer is beyond the scope of

this inspection.

Yes. A water hook-up is provided at the refrigerator opening = **Did Not Test**. WATER HOOK-UP: **BUILT-IN MICROWAVE:**

Functioning. The unit was turned on to check to see if heating occurred. The

temperature settings and timer were not evaluated.